


Copper Pipe Flaring: Common Mistakes and How to Avoid Them in HVAC and Plumbing Installations

Category: Refrigeration

written by www.mbsm.pro | 8 January 2026



Private Picture Copyright : WWW.MBSM.PRO

Mbsmpro.com, Copper Pipe, Flaring, HVAC, Plumbing, R600a, Mini-Split, Leak Prevention, Soft Copper, Flaring Block, 1/4", 3/8", 1/2", 5/8", Refrigerant Line

Mbsm.pro, Solutions, F0, Code, F0 Error, Gree, Mini Split, Air

Conditioner

Category: Solutions

written by www.mbsm.pro | 8 January 2026



Private Picture Copyright : WWW.MBSM.PRO

Mbsm.pro, Solutions, F0, Code, F0 Error, Gree, Mini Split, Air Conditioner

www.mbsm.pro, GREE , Mini Split , Air Conditioner ,Error Codes E6 , How To Fix

Category: Solutions,Tester ok

written by Jamila | 8 January 2026



The error E6 comes from the engine, it is the electronic engine card if it is an inverter range.

Communication error E6 Between Outside and inside