Mbsm.pro, PDF, File, MFTS-36HR, Air conditioner, 36000 BTU/h, 4.5 hp, r22

Category: Files
written by www.mbsm.pro | 8 March 2022

Mbsm.pro, PDF, File, MFTS-36HR, Air conditioner, 36000 BTU/h, 4.5 hp, r22

Mbsm.pro, GRee, air conditioner, GWHD(14)NK6LO(LC)(LH), GWHD(14)NK6LO, CB228W08401, CB228W08400, 14000 btu, Inverter Rotary, Compressor, QXA-B141zF030A, 2 hp-, 1440 w, lra 25 A, DC block controller, r410a, 220 v, 50 hz, 900 to 7200 RPM

TOSOT

QXA-B141zF030E

260-350V ⎓ 900-7200rpm R410A

LDB42DA428H0503

ZHUHAI LANDA COMPRESSOR CO., LTD.

Mbsm.pro, GRee, air conditioner, GWHD(14)NK6LO(LC)(LH), GWHD(14)NK6LO, CB228W08401, CB228W08400, 14000 btu, Inverter Rotary, Compressor, QXA-B141zF030A, 2 hp-, 1440 w, lra 25 A, DC block controller, r410a, 220 v, 50 hz, 900 to 7200 RPM

Mbsm.pro, Compressor, Hitachi, High Quality, Rotary, Sh356mv-C7nu, Air Conditioner, 2.4 HP, 19283 BTU, R22, 220 V, 1 PH, 5655 w

Category: compressor
written by www.mbsm.pro | 8 March 2022
Mbsm.pro, Compressor, Hitachi, High Quality, Rotary, Sh356mv-C7nu, Air Conditioner, 2.4 HP, 19283 BTU, R22, 220 V, 1 PH, 5655 w

LG rotary, compressor, model, QJS222PMA, 12700BTU 5.6Amps, EER = 10.7, air conditioner

Category: compressor
written by www.mbsm.pro | 8 March 2022
LG rotary, compressor, model, QJS222PMA, 12700BTU 5.6Amps, EER = 10.7, air conditioner

PH360G2C-4FTS1, 22000BTU, GMCC, Compressor rotary, 2 Ton, air conditioner, R22, refrigeration compressor , 50HZ 220V / 240V

Category: compressor
written by www.mbsm.pro | 8 March 2022

PH360G2C-4FTS1, 22000BTU, GMCC, Compressor rotary, air conditioner, R22, refrigeration compressor , 50HZ 220V / 240V

---

www.mbsm.pro, GREE , Mini Split , Air Conditioner ,Error Codes E6 , How To Fix

Category: Solutions,Tester ok
written by Jamila | 8 March 2022
The error E6 comes from the engine, it is the electronic engine card if it is an inverter range.
Communication error E6 Between Outside and inside