not recommended to replace compressor (Jiaxipera N1113Y) with (ACC HTK70AA).

Category: Refrigeration
written by www.mbsm.pro | 26 January 2026



Selecting the right compressor for a refrigeration system is critical for long-term performance and energy efficiency. When replacing a Jiaxipera N1113Y, simply matching the refrigerant type is not enough. This guide breaks down the technical differences between the N1113Y and the ACC HTK70AA, providing the essential data for professional technicians and refrigeration engineers.