

Mbsm.pro, COMPRESOR, TECUMSEH, BRASIL, 1/5 HP, TW1368YS, R-134, 1bp

Category: compressor
written by www.mbsm.pro | 12 January 2024



HP	Compresor	ERR Btu/Wh
1/8	THG1340YS	4,25
1/6	THG1352YS	4,40
1/5	THG1358YS	4,41
1/5+	TW1368YS	4,26
	TSA1374YS	4,90
1/4	TW1380YS	4,45
	TSA1380YS	5,10
	TPH1380YS	5,00





014 12.3
R134a
220V
220V
TW 140 - GS
TW 366YS
52 82471 10000

WARNING
To avoid burns,
IMMEDIATELY GET AWAY
if you hear, sizzling,
sputtering or popping inside
the compressor. Improper
service can lead to
explosion, fire or
injury. Service only by
qualified professional.

ADVERTENCIA
Para evitar quemaduras,
RETÍRESE INMEDIATAMENTE
si oír chisporroteo, zumbido
o explosión dentro del compresor.
El mantenimiento inadecuado
puede causar explosión, incendio
o explosión. Servicio
profesional autorizado.
No hacer los servicios
no autorizados.

ATENÇÃO
Para evitar queimaduras,
RETIRE-SE IMEDIATAMENTE
se ouvir sons de crepitação, ou
povo ou pipocamento dentro do
compressor. Manutenção incorreta
pode levar a explosão,
incêndio ou explosão. Serviço
profissional autorizado. Não
realizar serviços não autorizados.



HP	Compresor	ERR Btu/Wh
1/8	THG1340YS	4,25
1/6	THG1352YS	4,40
1/5	THG1358YS	4,41
1/5+	TW1368YS	4,26
	TSA1374YS	4,90
1/4	TW1380YS	4,45
	TSA1380YS	5,10
	TPH1380YS	5,00

