


Mbsm.pro, Solution, Error, E4, Beko, CNE50520DE, CNE 50520DE, Fridge, Freezer, No frost, 500 L, Compressor, r600a, 56 G, 1/5 hp, LBP, 160 w, 0.80 A, made in Turkey

Category: Refrigerator,Solutions
written by www.mbsm.pro | 5 October 2022



Private Picture Copyright : WWW.MBSM.PRO

Mbsm.pro, Solution, Error, E4, Beko, CNE50520DE, CNE 50520DE, Fridge, Freezer, No frost, 500 L, Compressor, r600a, 56 G, 1/5 hp, LBP, 160 w, 0.80 A, made in Turkey

Mbsm.pro, Solutions, air conditioner, Tornado, Error Code, E5

Category: Solutions

written by www.mbsm.pro | 5 October 2022



Private Picture Copyright : WWW.MBSM.PRO

Mbsm.pro, Solutions, air conditioner, Tornado, Error Code, E5

Mbsm.pro, Solutions, F0, Code, F0 Error, Gree, Mini Split, Air Conditioner

Category: Solutions

written by www.mbsm.pro | 5 October 2022




Private Picture Copyright : WWW.MBSM.PRO


Mbsm.pro, Solutions, F0, Code, F0 Error, Gree, Mini Split, Air Conditioner

Photos, Assemblage Machine A Linge, LG, 10kg

Category: Solutions, Technologie, Tester ok

written by www.mbsm.pro | 5 October 2022





REDMI NOTE 9
AWLED MILED MAHDIA

2021/2/18 10:43



● REDMI NOTE 9
● AWLED MILED MAHDIA

2021/2/18 10:52

Private Picture Copyright: WWW.MBSM.PRO



REDMI NOTE 9
AWLED MILAD MAHDY

2021/2/16 10:54



REDMI NOTE 9
AWLED MILED MAHDIA

2021/4/18



REDMI NOTE 9
AWLED MILED MAHDIA

2021/2/18 11:13



● ● REDMI NOTE 9
● ● AWLED MILED MAHDIA

Private Picture Copyright: WWW.MBSM.PRO




REDMI NOTE 9
AWLED MILED MAHDIA

2021/2/18 11:17



REDMI NOTE 9
AWLED MILED MAHDIA

2021/2/18 11:17






2021/2/18 10:54

Private Picture Copyright: WWW.MBSM.PRO





REDMI NOTE 9
AWLED MILED MARDIA

2021/2/18 11:13




Private Picture Copyright: WWW.MBSM.PRO



Private Picture Copyright: WWW.MBSM.PRO



Private Picture Copyright: WWW.MBSM.PRO



REDACTED NOTE 9
AWLED MILED MAHDIA

2021/2/18 12:20



REDMI NOTE 9
AWLED MILED MAHDIA

2021/2/18/12:31



REDMI NOTE 9
AWLED MILED MAHDIA

2021/2/18 12:31



REDMI NOTE 9
AWLED MILED MAHDIA

2021/2/18 12:31

Private Picture Copyright : WWW.MBSM.PRO

Traverse métallique haut de machine lave linge 10kg, Mesure et photos

Category: Solutions, Technologie
written by www.mbsm.pro | 5 October 2022



REDMI NOTE 9
AI DUAD CAMERA

Private Picture Copyright : WWW.MBSM.PRO



REDMI NOTE 9
AI QUAD CAMERA

Private Picture Copyright: WWW.MBSM.PRO



REDMI NOTE 9
AI QUAD CAMERA



Private Picture Copyright: WWW.MBSM.PRO



Private Picture Copyright: WWW.MBSM.PRO



Private Picture Copyright: WWW.MBSM.PRO



Private Picture Copyright: WWW.MBSM.PRO




Private Picture Copyright: WWW.MBSM.PRO



Private Picture Copyright: WWW.MBSM.PRO





Private Picture Copyright: WWW.MBSM.PRO



Private Picture Copyright: WWW.MBSM.PRO

Lave-linge, Samsung, code, Erreur, 3E, Changer ou réparer le moteur , Erreur charbon de démarrage

Category: Solutions

written by www.mbsm.pro | 5 October 2022



Le code erreur 3E apparaît sur une machine à laver Samsung, il est généralement dû à trop de vêtements dans la machine à laver, à un vêtement qui s'est coincé dans le tambour ou à une mauvaise connexion dans le faisceau de câbles.

Commencez par retirer certains vêtements de la machine et redémarrez la machine. Si vous obtenez toujours le code erreur 3E, vérifiez s'il y a un vêtement coincé dans le tambour et retirez-le. Si vous obtenez toujours le code erreur 3E après cela, avant de passer au point suivant, éteignez le lave-linge et éteignez-le en débranchant la prise de courant.

1. Retirez le panneau arrière de la machine à laver pour accéder au moteur du lave-linge. Débranchez et connectez les fils un par un pour vous assurer qu'il n'y a pas de mauvaise connexion.
2. Tout comme le moteur de la machine à laver peut avoir des mauvaises connexions, il en va de même pour le module de commande. Par conséquent,

vérifiez le câblage du module de commande et déconnectez-les et connectez-les un par un pour vous assurer qu'il n'y a pas de mauvaise connexion.

3. À l'arrière de la machine à laver, vous trouverez un capteur qui détecte la vitesse et la direction du tambour. Ce capteur peut également avoir une mauvaise connexion. Débranchez et connectez les fils sur ce capteur un par un.
4. Si vous avez vérifié ce qui précède et que votre lave-linge Samsung signal toujours le code erreur 3E, le moteur est probablement défectueux et doit être remplacé. Vous pouvez trouver un nouveau moteur pour votre lave-linge Samsung ici. Si vous ne trouvez pas un moteur dans la liste des produits qui correspond à votre lave-linge






Private Picture Copyright : WWW.MBSM.PRO




Private Picture Copyright : WWW.MBSM.PRO




Private Picture Copyright: WWW.MBSM.PRO




Private Picture Copyright: WWW.MBSM.PRO



Private Picture Copyright: WWW.MBSM.PRO



Private Picture Copyright: WWW.MBSM.PRO



Private Picture Copyright: WWW.MBSM.PRO

Pompe De Relevage Climatisation

Category: Solutions, Technologie

written by www.mbsm.pro | 5 October 2022

L'humidité de l'air se condense sur les surfaces froides. C'est notamment ce qui arrive avec les systèmes de climatisation. Il faut donc évacuer les « condensats ». Le plus simple et le plus fiable est de pouvoir les évacuer sous l'action de leur propre poids, de manière dite gravitaire. Mais ce n'est pas toujours possible.


Il faut alors utiliser une pompe de relevage de condensats qui va permettre d'aspirer l'eau et de la refouler vers une canalisation d'évacuation des eaux usées. Celle-ci peut dès lors se trouver au-dessus du bac de condensats du climatiseur. Il existe trois types de pompes pour les relevages de condensats de climatisation : à piston oscillant, centrifuges (débits importants) ou péri-staltiques (la compression d'un tube par un galet aspire les condensats). Généralement, pour les appareils courant, une pompe à piston suffit. C'est aussi le système le plus compact et discret.



Private Picture Copyright: WWW.MBSM.PRO



Private Picture Copyright: WWW.MBSM.PRO



Private Picture Copyright : WWW.MBSM.PRO



PDF , HVAC et Refrigeration Parts, Copper, Chemicals, Compressors, Controls, Coils, Fans & Motors, Electronics, Service Tools, Supplies

Category: Solutions,Technologie

written by www.mbsm.pro | 5 October 2022

PDF , HVAC et Refrigeration Parts, Copper, Chemicals, Compressors, Controls, Coils, Fans & Motors, Electronics, Service Tools, Supplies

Minisplit Climatiseur , Mirage, Galanz , Carte Mère CE-KFR48G

Category: Solutions,Technologie

written by www.mbsm.pro | 5 October 2022

Minisplit Climatiseur , Mirage, Galanz , Carte Mère CE-KFR48G

Refrigerant High &Low Pressure Temperature Chart ,R22 R410A ,R12 ,R134A ,R401A ,R409A ,R502 ,R404A ,R507A ,R408A ,R402A ,R600A

Category: Non classé,Solutions

written by www.mbsm.pro | 5 October 2022

Refrigerant High &Low Pressure Temperature Chart ,R22 R410A ,R12 ,R134A ,R401A ,R409A ,R502 ,R404A ,R507A ,R408A ,R402A ,R600A