Compressor, FLB075LBNA, LG-Original New Linear Refrigerator Compressor, LGcompresor, Inverter 0~220V 53Hz, R134a(165g), LSXC22386, LSXC22326, LSXC22336, 1/4HP

written by Lilianne | 17 October 2021
FLS075LANA is the new **compressor** model number It replaces these older **LG**/Kenmore Elite **compressor** versions: FC75LBNA FLA075LANA FLB075LANA FLB075LBNA

Compressor Fls075lana\_replacement A: Fla075lana, Flb075lana

Compressor, FLB075LBNA, LG-Original New Linear Refrigerator Compressor, LG-compresor, Inverter 0~220V 53Hz, R134a(165g), LSXC22386, LSXC22326, LSXC22336, 1/4HP

New version LG Compressor part # TCA38091801 & Software Jig TCA35911910

Compressor has a purple decal and red decal on top warning about the software update.

FLS075LANA is the new compressor model number
It replaces these older LG/Kenmore Elite compressor versions:
FC75LBNA
FLA075LANA
FLB075LANA

FLB075LBNA



Private Picture Copyright: WWW.MBSM.PRO



Private Picture Copyright: WWW.MBSM.PRO



SEARS BRANDS MANAGEMENT CORPORATION HOFFMAN ESTATES, IL 60179

HOUSEHOLD REFRIGERATOR/ REFRIGERATEUR MENAGERE

MODEL/MODELE:

795.73153.610

RATING/CAPACITÉ NOMINALE REFRIGERANT/RÉFRIGÉRANT 115V ~ 60Hz 2.9A

R134a 5.11oz

DEFROSTING INPUT / PUISSANCE ABSORBÉE EN DÉGIVRAGE 360W

POWER INPUT OF DEFROST HEATER /

PUISSANCE ABSORBÉE DE LA RÉSISTANCE DE DÉGIVRAGE

FREEZER/CONGÉLATEUR

350W

PRODUCTION DATE / DATE DE PRODUCTION 35 3/4(W) x 36 1/4(D) x 70 1/4(H) inch

2016.04

DIMENSIONS **DESIGN PRESSURES/** 

HIGH SIDE/ CÔTÉ SUPÉRIEUR 400PSI Ga

LOW SIDE/ CÔTÉ INFÉRIEUR 140PSI Ga

MADE IN KOREA FABRIQUÉ EN CORÉE

PRESSION DE DESSIN



TAB37097603





For SEARS REPAIR SERVICE CALL 1-844-553-6667 AU CANADA POUR SERVICE EN FRANÇAIS 1-800-LE-FOYER\*\* 24HOURS A DAY, 7 DAYS A WEEK FOR SEARS REPAIR SERVICE LE SERVICE DE REPARATION SEARS CANADA VINGT-QUATRE HEURES PAR JOUR. SEPT JOURS PAR SEMAINE





