

Mbsm.pro, Compressor, 1/4 hp, Aspera, Embraco NEK1121Z, LBP, R134a, NEK1121u, lbp, r290

Category: compressor

written by www.mbsm.pro | 27 December 2023



Private Picture Copyright : WWW.MBSM.PRO

Mbsm.pro, Compressor, 1/4 hp, Aspera, Embraco NEK1121Z, LBP, R134a, NEK1121u, lbp, r290

Mbsm.pro, Compressor, AE4430Z, R-404a, 1/4 HP , 230V, hbp

Category: compressor

written by www.mbsm.pro | 27 December 2023



Private Picture Copyright : WWW.MBSM.PRO

Mbsm.pro, Compressor, AE4430Z, R-404a, 1/4 HP , 230V, hbp

Mbsm.pro, Compressor, Qdh79g, 1/4 Hp,
205 w, Lbp, R134a, 220v, 1 phase 50
hz, QDH79G Refrigerator, 7.9 cm³

Category: compressor,expertise

written by www.mbsm.pro | 27 December 2023



Private Picture Copyright : WWW.MBSM.PRO

Mbsm.pro, Compressor, Qdh79g, 1/4 Hp, 205 w, Lbp, R134a, 220v, 1 phase 50 hz, QDH79G Refrigerator

Mbsm.pro, Refrigerator, Compressor, R600a S118CY1, 193 w, lbp, 1/4 hp

Category: compressor

written by www.mbsm.pro | 27 December 2023



Private Picture Copyright : WWW.MBSM.PRO

Mbsm.pro, Refrigerator, Compressor, R600a S118CY1, 193 w, lbp

Refrigerator, Embraco, Compressor, 1/4 hp, FF17.5HAK, FF18.5HAK , FFU70HAK, 1/3 hp, FG95HAK, FEU100HAK, 1/6 hp, EM65HNR, EMI50HEP, 1/5 hp, FG65HAK, FF165HAK, EMI70, EM20HHR, 1/12 hp, EM30HHR, 1/10 hp, EM40HEP, EM45HNR

Category: compressor,expertise

written by www.mbsm.pro | 27 December 2023



Private Picture Copyright : WWW.MBSM.PRO

Refrigerator, Embraco, Compressor, 1/4 hp, FF17.5HAK, FF18.5HAK , FFUZ0HAK, 1/3 hp, FG95HAK
FEU100HAK, 1/6 hp, EM65HNR, EMI50HEP, 1/5 hp, FG65HAK, FF165HAK, EMI70, EM20HHR, 1/12 hp,
EM30HHR, 1/10 hp, EM40HEP, EM45HNR,

Mbsm.pro, Refrigerant, Compressor,
R600a, GMCC, PZ90H1Y, SXF-562JA, 1 /
5hp, PZ110H1Y, 1/4 hp

Category: compressor

written by www.mbsm.pro | 27 December 2023



Private Picture Copyright : WWW.MBSM.PRO

Mbsm.pro, Refrigerant, Compressor, R600a, GMCC, PZ90H1Y, SXF-562JA, 1 / 5hp,
PZ110H1Y, 1/4 hp,

Mbsm.pro, Replaced, Jiaxisipera,
NS1121Y, 1/4 hp++, 1/3 hp-, 214Kcal,
R600a, 220V, with, Compressor,

hys69yq, 1/4 hp, lbp, r134a, HiTech, refrigerator, HSA 47542/1, SN-T, C467 – HC, Beko, 451 L, R600a, 64G

Category: compressor, Refrigerator
written by www.mbsm.pro | 27 December 2023



Private Picture Copyright : WWW.MBSM.PRO

Mbsm.pro, Replaced, Jiaxipera, NS1121Y, 1/4 hp++, 1/3 hp–, 214Kcal, R600a, 220V, with, Compressor, hys69yq, 1/4 hp, lbp, r134a, HiTech, refrigerator, HSA 47542/1, SN-T, C467 – HC, Beko, 451 L, R600a, 64G

Mbsm.pro, Jiaxipera, NS1121Y, 1/4 hp++, 1/3 hp–, 214Kcal, R600a, 220V

Category: compressor
written by www.mbsm.pro | 27 December 2023



Private Picture Copyright : WWW.MBSM.PRO

Mbsm.pro, Jiaxipera, NS1121Y, 1/4 hp++, 1/3 hp-, 214Kcal, R600a, 220V

Double-Door, Refrigerator, BCD-498, compressor, 1/4 hp, r134a, 135G

Category: Refrigerator

written by www.mbsm.pro | 27 December 2023

Specification	
Capacity(L)	498
Freezer Capacity(L)	136
Refrigerator Capacity(L)	362
Climate	N/ST/T
Refrigerant	R600a/R134a
Approval	CE,CB
Net W*D*H(mm)	700x695x1776mm
Packing W*D*H(mm)	762x725x1817mm
Loading Quantity 40°C	67
Standard Features	
Low noise operation, quiet preservation.	Intimate design, ingenious quality.
Temperature control multi gear adjustment	Microcellular foam is long and fresh.
Double width design, stable operation	Store fresh in different areas and adjust as you please
Strong refrigeration, energy saving and environmental	protection




Private Picture Copyright : WWW.MBSM.PRO

Double-Door, Refrigerator, BCD-498, compressor, 1/4 hp, r134a, 135G

Compressor, tw1380ys, r134, Ariston, refrigerator, 1/4 hp, Lbp

Category: compressor

written by www.mbsm.pro | 27 December 2023



R134a LRA:14.0
220-230V ~ 60 Hz
200-220V ~ 50 Hz

TW150 - MS - 410
TW1380YS

51 A1006 21 010133

CE

COUNTRY OF ORIGIN: BRAZIL THERMALLY PROTECTED

WARNING

To avoid burns, immediately get away if you hear, sizzling, rattling or popping inside the compressor. Improper servicing can lead to explosion, fire or electrical shock. Service only by trained professional.

ADVERTENCIA

Para evitar quemaduras, RETIRESE INMEDIATAMENTE al oír chisporroteos, siseos o estallidos dentro del compresor. El mantenimiento inadecuado puede causar electrocución, incendio o explosión. Solamente profesionales entrenados pueden hacer los servicios de mantenimientos.

ATENÇÃO

Para evitar queimaduras, RETIRE-SE IMEDIATAMENTE se ouvir sons de crepitação, talsos ou pipocamento dentro do compressor. Manutenção inadequada pode levar à explosão, incêndio ou choque elétrico. Somente profissionais treinados podem realizar serviços de manutenção.

Private Picture Copyright : WWW.MBSM.PRO

Compressor, tw1380ys, r134, Ariston, refrigerator, 1/4 hp, Lbp