

Mbsm.pro, PDF, File, MFTS-36HR, Air conditioner, 36000 BTU/h, 4.5 hp, r22

Category: Files

written by www.mbsm.pro | 8 March 2022



Private Picture Copyright: WWW.MBSM.PRO

Mbsm.pro, PDF, File, MFTS-36HR, Air conditioner, 36000 BTU/h, 4.5 hp, r22

Mbsm.pro, Gree, air conditioner,
GWHD(14)NK6L0(LC)(LH), GWHD(14)NK6L0,
CB228W08401, CB228W08400, 14000 btu,
Inverter Rotary, Compressor, QXA-
B141zF030A, 2 hp-, 1440 w, I_{ra} 25 A,
DC block controller, r410a, 220 v, 50
hz, 900 to 7200 RPM

Category: air conditioner,compressor
written by www.mbsm.pro | 8 March 2022

TOSOT

QXA-B141zF030E

260-350V 900-7200rpm R410A



LDB42DA428H0503

ZHUHAI LANDA COMPRESSOR CO., LTD.

Mbsm.pro, GRee, air conditioner, GWHD(14)NK6L0(LC)(LH), GWHD(14)NK6L0, CB228W08401, CB228W08400, 14000 btu, Inverter Rotary, Compressor, QXA-B141zF030A, 2 hp-, 1440 w, lra 25 A, DC block controller, r410a, 220 v, 50 hz, 900 to 7200 RPM

Mbsm.pro, Compressor, Hitachi, High Quality, Rotary, Sh356mv-C7nu, Air Conditioner, 2.4 HP, 19283 BTU, R22, 220 V, 1 PH, 5655 w

Category: compressor

written by www.mbsm.pro | 8 March 2022



Private Picture Copyright: WWW.MBSM.PRO

Mbsm.pro, Compressor, Hitachi, High Quality, Rotary, Sh356mv-C7nu, Air Conditioner, 2.4 HP, 19283 BTU, R22, 220 V, 1 PH, 5655 w

LG rotary, compressor, model,
QJS222PMA, 12700BTU 5.6Amps, EER =
10.7, air conditioner

Category: compressor

written by www.mbsm.pro | 8 March 2022

QJS222PMA CONDENSERS

THERMALLY PROTECTED R22

1PH 50Hz 220-240 V ~ LRA 29

SERIAL NO. 0E1R1184ED23 - A00124



LG



MADE IN THAILAND

WARNING

Service should be performed by trained personnel only.



ELECTRIC SHOCK HAZARD

- Ground the equipment securely.
- Turn off the power before servicing.
- Retain Terminal Cover in position whenever power is applied to this compressor.



BURN HAZARD

- Do not touch the Compressor with bare hands during operation or after stoppage instantly.



EXPLOSION OR FIRE

- Wear safety goggles and gears as system contains oil and refrigerant under pressure.
- Do not compress air.
- Do not use refrigerant and lubricants besides those specified.
- Make sure to connect right way with valves.

SHOT ON MI 9T
AI TRIPLE CAMERA

2021/4/10 21:28

Private Picture Copyright: WWW.MBSM.PRO

LG rotary, compressor, model, QJS222PMA, 12700BTU 5.6Amps, EER = 10.7, air conditioner

PH360G2C-4FTS1, 22000BTU, GMCC, Compressor rotary, 2 Ton, air conditioner, R22, refrigeration compressor , 50HZ 220V / 240V

Category: compressor

written by www.mbsm.pro | 8 March 2022



Private Picture Copyright : WWW.MBSM.PRO

PH360G2C-4FTS1, 22000BTU, GMCC, Compressor rotary, air conditioner, R22, refrigeration compressor , 50HZ 220V / 240V

www.mbsm.pro, GREE , Mini Split , Air Conditioner ,Error Codes E6 , How To Fix

Category: Solutions,Tester ok

written by Jamila | 8 March 2022



The error E6 comes from the engine, it is the electronic engine card if it is an inverter range.

Communication error E6 Between Outside and inside