


Compressor, tw1380ys, r134, Ariston, refrigerator, 1/4 hp, Lbp

Category: compressor

written by www.mbsm.pro | 11 November 2023



R134a LRA:14.0
220-230V ~ 60 Hz
200-220V ~ 50 Hz



TW150 - MS - 410
TW1380YS



CE

51 A1006 21 010133
COUNTRY OF ORIGIN: BRAZIL THERMALLY PROTECTED

WARNING
To avoid burns
IMMEDIATELY GET AWAY
if you hear, sizzling,
spattering or popping inside
the compressor. Improper
servicing can lead to
electrocution, fire or
explosion. Service only by
trained professional.

ADVERTENCIA
Para evitar quemaduras,
RETIRESE INMEDIATAMENTE
al oír chisporroteos, siseos o
estallidos dentro del compresor.
El mantenimiento inadecuado
puede causar electrocución,
incendio o explosión. Solamente
profesionales entrenados
pueden hacer los servicios de
mantenimientos.

ATENÇÃO
Para evitar queimaduras,
RETIRE-SE IMEDIATAMENTE
se ouvir sons de crepitação,
taícos ou pipocamento dentro do
compressor. Manutenção inade-
quada pode levar à electrocuição,
incêndio ou explosão. Somente
profissionais treinados podem
realizar serviços de manutenção.

Private Picture Copyright : WWW.MBSM.PRO

Compressor, tw1380ys, r134, Ariston, refrigerator, 1/4 hp, Lbp

Mbsm.pro, COMPRESSOR, HYK95AA, 240V, 1/5HP, 167W, R600, ARISTON, FREEZER

Category: compressor

written by Jamila | 11 November 2023



REDMI NOTE 9
AI QUAD CAMERA

2022/10/1 18:54

Mbsm.pro, COMPRESSOR, HYK95AA, 240V, 1/5HP, 167W, R600, ARISTON, FREEZER

Mbsm.pro, Freezer, Ariston, ECH240s1, 240 L, Compressor, TECUMSEH BRASIL, THb1355y, 1/5 hp, LBP, R134A, 100g, replaced by, egm70af, gl70aa, capillarie 0.026, 1.2 m, Alert -10

Category: Archivation,compressor,expertise,Freezer
written by www.mbsm.pro | 11 November 2023



Mbsm.pro, Freezer, Ariston, ECH240s1, 240 L, Compressor, TECUMSEH BRASIL, THb1355y, 1/5 hp, LBP, R134A, 100g, replaced by, egm70af, gl70aa, capillarie 0.026, 1.2 m, Alert -10

Mbsm.pro, Compressor, tw1390ys,

tw160-ms-472, Tecumseh, TW160KS ,
r134a, Ariston, Indesit, lbp, 1/3 hp,
220 v

Category: compressor

written by www.mbsm.pro | 11 November 2023



Mbsm.pro, Compressor, tw1390ys, tw160-ms-472, Tecumseh, TW160KS , r134a, Ariston, Indesit, lbp, 1/3 hp,

Mbsm.pro, Compressor, EMBRACO, NBM1119Y, Indesit, Ariston, ASPERA, R600, 1/3 HP, 237W, LBP

Category: compressor

written by www.mbsm.pro | 11 November 2023



Private Picture Copyright : WWW.MBSM.PRO

Compressor	EMBRACO
Template	NBM1119Y
Height (mm)	
Gas	R600a
Voltage	200-240V 50Hz / 230V 60Hz
Application	LBP (Low Back Pressure)
Test Condition	ASHRAE LBP 32
Displacement	14.28 of the Italian Civil Code
Motor	RSIR
Power (HP)	
Cap. Frigor. Watt	233
Cap. Frigor. Kcal	200
Cap. Frigor. Btu / h	795
COP (W / W)	1.44

Watt absorbed (W)

Device of Avv. PTC

Capacitor

Cooling type

Packaging (Pcs / Pallet)



Private Picture Copyright: WWW.MBSM.PRO

Mbsm_dot_pro_private_PDF_NBM1119YTélécharger



Private Picture Copyright: WWW.MBSM.PRO

**L111CYA, COMPRESSOR, ASSY, Indesit ,
Ariston, whirlpool, 1/5hp, lbp, 180W,
r600a**

Category: compressor

written by www.mbsm.pro | 11 November 2023



REDMI NOTE 8 PRO
AI QUAD CAMERA

Private Picture Copyright : WWW.MBSM.PRO



REDMI NOTE 8 PRO
AI QUAD CAMERA

Private Picture Copyright : WWW.MBSM.PRO

WARNING


Electrical Shock Hazard



Disconnect power before servicing.
 Any ground circuit disconnected during service must be reconnected.
 Do not reconnect unit to electrical supply until compressor terminal cover is securely in place.
 If refrigerant leak is suspected around compressor terminal, relieve all pressure from the system, keeping terminal, cover in place.
 Failure to do so can result in death or electrical shock.

FREQUENCY	50 Hz
VOLTAGE RANGE	220-240VAC
INPUT WATTS	710 W
INPUT CURRENT	3.5 A
COMFORT WATTS	600 W
COOLING CAPACITY	AS PER TABLE
CLIMATE CLASS	T

Do Not service with R134a
 Follow only Approved R600a service procedure & a Qualified technician while repairing



Risk of fire



WARNING


Caution: Risk of fire
 Always observe the following points of caution when repairing or servicing the refrigerator since the refrigerant is a flammable gas.
 Avoid using any flame or heat source to service the sealed system when the unit is still charged with refrigerant.
 In the event of refrigerant leak, fully vent the area before recharging the unit.
 Never use acid to measure the refrigerant gas leak.

BLOWING AGENT: R600a (ISOTHERM)
 C.F.L. (CYCLO PENTANE) AS PER TABLE

MFG. BY: WHIRLPOOL OF INDIA LTD.
 PLOT NO. A-4, M.D.C.
 KARKANAGAN, TAL. SHIBPUR,
 DIST. PUNE - 412 204

"WHIRLPOOL" IS A REGISTERED TRADEMARK OF "WHIRLPOOL CORPORATION USA"

WIRING DIAGRAM



SYMBOL CODE

- ⊕ CONNECTOR - SCREW ON
- ⊖ CONNECTOR - CLOSED END
- DISCONNECT TERMINAL
- PERMANENT CONNECTION
- ⊕ PLUS CONNECTOR
- ⊖ GROUND JUMPER (CHASSIS)

WIRE COLOR CODE

- GR = GREEN
- BL = BLUE
- BR = BLACK
- RD = RED
- WH = WHITE
- YL = YELLOW
- OR = ORANGE
- PK = PINK
- LT = LIGHT
- VT = VIOLET
- SL = SILVER
- BRN = BROWN
- BLK = BLACK
- BLU = BLUE

NAME	MODEL	GROSS CAPACITY	STORAGE CAPACITY	REFRIGERANT (R600a) (ISOTHERM)
L15C000A	WT1011TU R1	460L	400L	1.131KG
				70

WT1175029

REDMI NOTE 8 PRO
 AI QUAD CAMERA



REDMI NOTE 8 PRO
AI QUAD CAMERA

Private Picture Copyright : WWW.MBSM.PRO

E	E1130DZ	CSIR	220/60	390	1.35	F	NE	NE6213CK	CSF
	EU1121DZ	RSCR	220/60	325	1.52	F		NE6213BK	CSF
S	SK35XZ	RSIR	127/60	88	1.38	S	CT	CT6217CK	CSF
L	LU65XZ	RSIR	127/60	190	1.52	S		CT6220CK	CSF
E	EU1121XZ	CSIR	127/60	250	1.50	F	CJ	CJ6228CK	CSF
R600a L.B.P 宽电压								CJ6232CK	CSF
S	S66CY	RSIR	160~260/50	108	1.20		L.P	CJ6240CK	CSF
	SG66CY	RSIR	160~260/50	108	1.40			ES8CU	RSIF
	SU66CY	RSCR	160~260/50	108	1.60			EN32CU	RSIF
	SZ66CY	RSCR	160~260/50	108	1.70			LZ58CU	RSCF
L	L88CYA	RSIR	160~260/50	155	1.36	S	R290 H.B.P		
	L111CYA	RSIR	160~260/50	185	1.40	S	NB	NB5175CU	RSIF
	LK76CYA	RSCR	160~260/50	142	1.50	S	NE	NE5195CU	RSIF
	LK88CYA	RSCR	160~260/50	155	1.50	S			

Private Picture Copyright: WWW.MBSM.PRO

Mbsm_dot_pro_private_PDF_L111CYATélécharger