

Mbsm.pro, Solutions, F0, Code, F0 Error, Gree, Mini Split, Air Conditioner

Category: Solutions

written by www.mbsm.pro | 20 September 2022



Private Picture Copyright : WWW.MBSM.PRO

Mbsm.pro, Solutions, F0, Code, F0 Error, Gree, Mini Split, Air Conditioner

Danfoss, Compressor, 5 Hp, R22, Démontage, ouverture, DESTRUCTION

Category: compressor

written by www.mbsm.pro | 20 September 2022

Danfoss Commercial
Compressors

Model no: MT64HM4D



Serial no: EC1006958089



Danfoss

MADE IN FRANCE

380-400V 3~ 50 Hz

460V 3~ 60 Hz

UL LISTED

LR 64A 14A MAX

UL LISTED

THERMALLY PROTECTED

P.E.D.

Marking LP side HP side

PS 18.4 bar 27.8 bar

TS max 50 °C 68 °C

TS min -35 °C -35 °C

Volume 16.5 l 0.6 l

Lubricant: MINERAL OIL 160 P



CE 0038 EAC

OPPO F11 · © Karim Sleim ❤️ Joanna

Private Picture Copyright: WWW.MBSM.PRO

Danfoss Commercial
Compressors

Model no: MT64HM4D



Serial no: EC1006958089



Danfoss

MADE IN FRANCE

380-400V 3~ 50 Hz

460V 3~ 60 Hz

UL LISTED

LR 64A 14A MAX

UL LISTED

THERMALLY PROTECTED

P.E.D.

Marking LP side HP side


PS 18.4 bar 27.8 bar

TS max 50 °C 68 °C

TS min -35 °C -35 °C

Volume 16.5 l 0.6 l

Lubricant: MINERAL OIL 160 P



CE 0038 EAC

OPPO F11 · © Karim Sleim ❤️ Joanna

Refrigerant: R22/134a


Private Picture Copyright: WWW.MBSM.PRO

Product: Compressor
产地: 法国制造
Plant: Made in France
客服: 丹佛斯自动控制管理(上海)有限公司
Customer service: Danfoss Automatic Controls Management (Shanghai) Co.Ltd
地址电话: 上海市宜山路900号科技大楼C楼20层200233/(021)61513000
Address/Tel: 20th Floor, Block C, Hi-Tech Building
900 Yi Shan Road Shanghai 200233/(021)61513000
警告: 只有具备一定经验和安全程序
培训的授权人员才可以进行安装和维修。
Warning: The installation and maintenance
should be performed by the authorized
person only

Danfoss

Danfoss Commercial Compressors

型号: MT64HM4DVE



序列号: EC1006983516

制冷剂: R22 或 R417A 仅和 160PZ

WARNING

Manufacturing and servicing shall be performed by trained
authorized only. Failure to do so could result in serious injury or
death. ELECTRIC SHOCK HAZARD: Turn off power before removing the
cover of compressor. Remove the power plug and/or switch off the
power supply. Compressor contains refrigerant and oil under pres-
sure. Always release pressure from both the high and low side before
removing the cover. Use a suitable refrigerant recovery unit to remove
refrigerant.

产地: 法国

380-400V 3~ 50 Hz

460V 3~ 60 Hz

旋转电流: 64A 最大工作电流: 14A

过热保护

低压侧

最高极限压力 18.4 bar

最高极限温度 50 °C

最低极限温度 -35 °C

润滑油: MINERAL OIL 160 P



Maneurop
RECIPROCATING COMPRESSOR

CAUTION

Use only manufacturer's approved refrigerants,
bulbs and other components. Under-charge
refrigerant / overcharge / electrical component could
cause fire, explosions, electrical shorting.



For details refer to multi-language instruction
book and technical documents, if any, available on
Danfoss website at <http://http://www.danfoss.com>

Private Picture Copyright: WWW.MBSM.PRO



Private Picture Copyright : WWW.MBSM.PRO



Private Picture Copyright: WWW.MBSM.PRO





Private Picture Copyright: WWW.MBSM.PRO



Private Picture Copyright: WWW.MBSM.PRO



Private Picture Copyright: WWW.MBSM.PRO

Lave-linge, Samsung, code, Erreur, 3E, Changer ou réparer le moteur , Erreur charbon de démarrage

Category: Solutions

written by www.mbsm.pro | 20 September 2022



Le code erreur 3E apparaît sur une machine à laver Samsung, il est généralement dû à trop de vêtements dans la machine à laver, à un vêtement qui s'est coincé dans le tambour ou à une mauvaise connexion dans le faisceau de câbles.

Commencez par retirer certains vêtements de la machine et redémarrez la machine. Si vous obtenez toujours le code erreur 3E, vérifiez s'il y a un vêtement coincé dans le tambour et retirez-le. Si vous obtenez toujours le code erreur 3E après cela, avant de passer au point suivant, éteignez le lave-linge et éteignez-le en débranchant la prise de courant.

1. Retirez le panneau arrière de la machine à laver pour accéder au moteur du lave-linge. Débranchez et connectez les fils un par un pour vous assurer qu'il n'y a pas de mauvaise connexion.
2. Tout comme le moteur de la machine à laver peut avoir des mauvaises connexions, il en va de même pour le module de commande. Par conséquent, vérifiez le câblage du module de commande et déconnectez-les et connectez-les un par un pour vous assurer qu'il n'y a pas de mauvaise connexion.
3. À l'arrière de la machine à laver, vous trouverez un capteur qui détecte la vitesse et la direction du tambour. Ce capteur peut également avoir une mauvaise connexion. Débranchez et connectez les fils sur ce capteur un par un.
4. Si vous avez vérifié ce qui précède et que votre lave-linge Samsung signal toujours le code erreur 3E, le moteur est probablement défectueux et doit être remplacé. Vous pouvez trouver un nouveau moteur pour votre lave-linge Samsung ici. Si vous ne trouvez pas un moteur dans la liste des produits qui correspond à votre lave-linge



Private Picture Copyright: WWW.MBSM.PRO



Private Picture Copyright: WWW.MBSM.PRO




Private Picture Copyright : WWW.MBSM.PRO




Private Picture Copyright : WWW.MBSM.PRO




Private Picture Copyright: WWW.MBSM.PRO



Private Picture Copyright: WWW.MBSM.PRO



Private Picture Copyright: WWW.MBSM.PRO



Private Picture Copyright: WWW.MBSM.PRO



Private Picture Copyright: WWW.MBSM.PRO