

LOW BACK PRESSURE ,HITACHI ,  
Compressor FL1257-SR , 1/5HP , R134a  
,135 W , BTU/Hr 512 ,Curcuit RSIR

Category: Solutions,Tester ok  
written by [www.mbsm.pro](http://www.mbsm.pro) | 23 April 2020


HITACHI FL1257-SD

220-240V 50Hz OIL 2006.05.13



SERIAL NO.09760

HFC-134a



WARNING HIGH TEMPERATURE  
ELECTRIC SHOCK

K12

DO NOT TOUCH



SHOT ON M6T  
MEIZU

PictureS Mbsm Dot Pro : [www.mbsm.pro](http://www.mbsm.pro)

LOW BACK PRESSURE ,HITACHI , Compressor FL1257-SR , 1/5HP , R134a ,135 W ,  
BTU/Hr 512 ,Curcuit RSIR