

# Mbsm.pro ، تأمين الأجهزة ، Lockout Tagout ، المعدات الكهربائية ، نظام السلامة المهنية

Category: Arabe,Développement,Technologie  
written by www.mbsm.pro | 23 April 2019





Mbsm Dot Pro : [www.mbsm.pro](http://www.mbsm.pro)

.غلق بمشبك قابل للطي ، مما يسمح لستة أقفال لقفل جهاز واحد أو القفل والعلامة هو إجراء أمان يستخدم في إعدادات الصناعة والبحث للتأكد من أن الآلات الخطرة مغلقة بشكل صحيح ولا يمكن تشغيلها مرة أخرى قبل الانتهاء من أعمال الصيانة أو الإصلاح. يتطلب الأمر عزل " **مصدر الطاقة الخطرة** وجعلها غير صالحة للعمل" قبل بدء العمل في المعدات المعنية. يتم بعد ذلك قفل مصادر الطاقة المعزولة ووضع علامة على القفل تحدد العامل الذي وضعه. عندها يمسك العامل بمفتاح القفل ، مما يضمن أنه فقط هو أو هي قادر على إزالة القفل وبهذه تشغيل الجهاز. هذا يمنع بدء التشغيل العرضي لجهاز ما عندما يكون في حالة خطرة أو عندما يكون العامل على اتصال مباشر به .<sup>[1]</sup>

في مختلف الصناعات كوسيلة آمنة للعمل على المعدات الخطرة Lockout-tagout يستخدم .ويفرضه القانون في بعض البلدان

---

## www.mbsm.pro, Electrolux GL75AA Refrigerator 1/5 HP, Compressor Cooling solution for Refrigerators

Category: Technologie,Tester ok  
written by Jamila | 23 April 2019



PictureS Mbsm Dot Pro : [www.mbsm.pro](http://www.mbsm.pro)

www.mbsm.pro, Electrolux GL75AA Refrigerator 1/5 HP, Compressor Cooling solution for Refrigerators

---

# [www.mbsm.pro](http://www.mbsm.pro) , LG MA42LBJG Refrigerator Compressor 1/6 Hp , Cooling solution for Refrigerators

Category: Technologie,Tester ok  
written by Jamila | 23 April 2019



[www.mbsm.pro](http://www.mbsm.pro)

Cooling solution for Refrigerators & Commercial Appliances This M-series reciprocating LBP compressor provides complete cooling solution for Domestic & Commercial refrigeration appliances. Compact Size, Silent operation, Low Voltage start ability (LVS) are its prominent features. M-Series compressor caters to 6s quality assurance and has globally proven reliability.

---

## [www.mbsm.pro](http://www.mbsm.pro) , Code Erreur E2 , Machine a Laver Benken

Category: Plomberie,Solutions  
written by mahdi miled | 23 April 2019  
Le Code d'erreur E2 est suite au blocage d'eau au petit filtre a l'entree d'eau ou absence d'eau ou panne de vanne