Mbsm.pro, Solutions, F0, Code, F0 Error, Gree, Mini Split, Air Conditioner

Category: Solutions

written by www.mbsm.pro | 20 September 2022



Mbsm.pro, Solutions, F0, Code, F0 Error, Gree, Mini Split, Air Conditioner

www.mbsm.pro, GREE , Mini Split , Air Conditioner ,Error Codes E6 , How To Fix

Category: Solutions, Tester ok

written by Jamila | 20 September 2022

The error E6 comes from the engine, it is the electronic engine card if it is an inverter range.

Communication error E6 Between Outside and inside