

LOW BACK PRESSURE ,HITACHI ,
Compressor FL1257-SR , 1/5HP , R134a
,135 W , BTU/Hr 512 ,Curcuit RSIR

Category: Solutions,Tester ok
written by www.mbsm.pro | 23 April 2020

HITACHI FL1257-SD


220-240V 50Hz OIL 2006.05.13



(P)

SERIAL NO.09760

HFC-134a



WARNING HIGH TEMPERATURE
ELECTRIC SHOCK

K12

DO NOT TOUCH




SHOT ON M6T
MEIZU

HITACHI FL1257-SD

220-240V 50Hz OIL 2006.05.13



SERIAL NO.09760 HFC-134a



WARNING HIGH TEMPERATURE
ELECTRIC SHOCK

K12

DO NOT TOUCH



SHOT ON M6T
MEIZU