

# Mbsm.pro, Compressor, C-R191H5C, Sanyo, 24000BTU, air conditioner compressor, r22, 2 ton

Category: expertise

written by [www.mbsm.pro](http://www.mbsm.pro) | 14 April 2022

**SANYO**



MODEL C-R191H5C  
CODE 80649745

QC PASSED



CHINA RESOURCES SANYO (SHENYANG) COMPRESSOR CO., LTD.  
沈阳华润三洋压缩机有限公司

**WARNING-SERVICEMAN**

- 1. FIELD SERVICE LEAK TEST PRESSURE MUST NOT EXCEED 10.5KG FCM/G.
- 2. THIS COMPRESSOR MUST BE GROUNDED.
- 3. DO NOT OPERATE WITHOUT PROTECTIVE COVER OVER TERMINALS.
- DISCONNECT ALL POWER BEFORE REMOVING THE PROTECTIVE COVER.

**CAUTION**

COMPRESSOR HOUSING MAY REACH 150°C WITH THERMAL PROTECTOR  
APPROVED BY SANYO AND TESTED IN ACCORDANCE WITH DIN TUV


**SANYO**



MODEL C-R191H5C

CODE 80649745

QC PASSED



CHINA RESOURCES SANYO (SHENYANG) COMPRESSOR CO., LTD.

沈阳华润三洋压缩机有限公司

**WARNING-SERVICEMAN**

1. FIELD SERVICE LEAK TEST PRESSURE MUST NOT EXCEED 10.5KG /CM<sup>2</sup> G.
2. THIS COMPRESSOR MUST BE GROUNDED.
3. DO NOT OPERATE WITHOUT PROTECTIVE COVER OVER TERMINALS.  
DISCONNECT ALL POWER BEFORE REMOVING THE PROTECTIVE COVER.

**CAUTION**

COMPRESSOR HOUSING MAY REACH 150°C WITH THERMAL PROTECTOR  
APPROVED BY SANYO AND TESTED IN ACCORDANCE WITH DIN TUV.