


Mbsm.pro, compressor, BRE4-0750-TFD-510, Copeland, 7.5 HP, 460V, 3 PH, R22, R134A, R407C, Scroll Compressor, Copeland Compressor

written by Lilianne | 23 January 2024




Private Picture Copyright : WWW.MBSM.PRO

Mbsm.pro, compressor, BRE4-0750-TFD-510, Copeland, 7.5 HP,
460V, 3 PH, R22, R134A, R407C, Scroll Compressor, Copeland
Compressor

Mbsm.pro, Donper, Compressor, R600A, L88CY, 1/5 hp, 1bp

written by Lilianne | 23 January 2024

 Condor



RoHS

<http://www.donper.com>



220320003580102311

L88CY1

220~240V~50Hz 1PH
THERMALLY PROTECTED



RoHS



Warning: Risk of fire

Mbsm.pro, Donper, Compressor, R600A, L88CY, 1/5 hp, 1bp

**Mbsm.pro, Bristol,
Compressor, H24B17QABJA,
17000 btu, 1.5 hp, r22,
Capillary Size (0.060),
Capillary Length 33"**

written by Lilianne | 23 January 2024



Private Picture Copyright : WWW.MBSM.PRO

Mbsm.pro, Bristol, Compressor, H24B17QABJA, 17000 btu, 1.5 hp,

r22, Capillary Size (0.060), Capillary Length 33"

**Mbsm.pro, compressor, Sanyo,
Rotary, Split system air
conditioner, Compressors, C-
R221H5S, S6231526791, 24000
btu, R22, 3 hp, 2 ton**

written by Lilianne | 23 January 2024

SANYO



MODEL C-R221H5S

CODE 80687145



CHINA RESOURCES SANYO (SHENYANG) COMPRESSOR CO., LTD.
沈阳三洋压缩机有限公司

WARNING-SERVICEMAN

1. FIELD SERVICE LEAK TEST PRESSURE MUST NOT EXCEED 40 PSI (2.7 MPa).
 2. THIS COMPRESSOR MUST BE GROUNDED.
 3. DO NOT OPERATE WITHOUT PROTECTIVE COVER OVER TERMINALS.
- DISCONNECT ALL POWER BEFORE REMOVING THE PROTECTIVE COVER.

CAUTION

COMPRESSOR HEATING MAY REACH 150°C WITH THERMAL PROTECTION.
APPROVED BY SANYO AND TESTED IN ACCORDANCE WITH JIS T3A.

R22, 3 hp, 2 ton

**Mbsm.pro, compressors,
DZ120V1A, DZ120V1V, DZ120V1B,
inverter, blcd, from 1320 to
4320 rpm, from 82 to 265 w
input, cooling 293 btu to 904
, 1/3 hp, r600a, lbp**

written by Lilianne | 23 January 2024




Private Picture Copyright : WWW.MBSM.PRO

Mbsm.pro, compressors, DZ120V1A, DZ120V1V, DZ120V1B, inverter, blcd, from 1320 to 4320 rpm, from 82 to 265 w input, cooling 293 btu to 904 , 1/3 hp, r600a, lbp

Mbsm.pro, compressor, Secop, SC18CLX.2, 104L2197, Danfoss R404A, R507, 3/4 hp, lbp

written by Lilianne | 23 January 2024



Private Picture Copyright : WWW.MBSM.PRO

Mbsm.pro, compressor, Secop, SC18CLX.2, 104L2197, Danfoss R404A, R507, 3/4 hp, lbp

**Mbsm.pro, Toshiba, Rotary,
refrigerator ,compressor,
PH360X3C-4KTS1, 1.5T++, 2,5
hp, 1 ph, r22**

written by Lilianne | 23 January 2024



Mbsm.pro, Toshiba, Rotary, refrigerator ,compressor,
PH360X3C-4KTS1, 1.5T++, 3 hp, 1 ph, r22

**Mbsm.pro, Compressor,
EA65H1E-U, 1/3 hp++, mbp,
r290, freezer, with two
doors, GMCC Refrigeration
Compressor**

written by Lilianne | 23 January 2024



Mbsm.pro, Compressor, EA65H1E-U, 1/3 hp++, mbp, r290, freezer,
with two doors, GMCC Refrigeration Compressor

**Mbsm.pro, 104L2848, SC15CM,
COMPRESSOR, DANFOSS, 1/2 hp,
r22, LBP**

written by Lilianne | 23 January 2024



Mbsm.pro, 104L2848, SC15CM, COMPRESSOR, DANFOSS, 1/2 hp, r22,
LBP

**Mbsm.pro, Compressor,
Tecumseh, 1/2 hp, CAE9470Z,
(P0E), HBP, R404A,
220-240V/1/50Hz , replaced by
AE4470Z**

written by Lilianne | 23 January 2024



Mbsm.pro, Compressor, Tecumseh, 1/2 hp, CAE9470Z, (P0E), HBP,
R404A, 220-240V/1/50Hz , replaced by AE4470Z