

R134a, FL1568-SL, HITACHI Compressor, 220 v 50Hz, 1/4 Hp, white whale, 18Feet, LBp, 200W

Category: compressor

written by www.mbsm.pro | 26 May 2020

14/8/2556		OVERLOAD RELAY - Hitachi Compressor (Thailand) _Ltd_.htm										
	FL0739-S*	3.9	94	81	321	270	St		RSIR	7.8	179	
	FL0845-S*	4.5	117	100	400	270	St		RSIR	8.1	179	
	FL1052-S*	5.2	121	104	413	270	St		RSIR	8.3	179	
	FL1152-S*	5.2	136	117	464	260	St		RSCR	8.3	179	
	FL1152-S*	5.2	134	115	457	280	St		RSIR	9.3	188	
220-240V	FL1157-S*	5.7	136	117	464	240	St		RSIR	8.7	178	
50Hz	FL1257-S*	5.7	150	129	512	240	St		RSIR	9.3	181	
	FL1257-S*	5.7	173	148	591	240	St		RSCR	9.3	181	
	FL1262-S*	6.2	145	124	495	310	St		RSIR	10.5	200	
	FL1462-S*	6.2	165	142	563	310	St		RSIR	10.5	200	
	FL1462-S*	6.2	185	159	632	310	St		RSCR	11.9	216	
	FL1568-S*	6.8	180	154	615	310	St		CSIR	11.5	216	
	FL1568-S*	6.8	200	172	683	310	St		RSIR	10.5	200	
	FL1568-S*	6.8	200	172	683	310	St		RSCR	10.5	200	
	FL1875-S*	7.5	215	184	734	335		OC	RSIR	10.8	211	
	FL1875-S*	7.5	208	178	710	310			F	RSIR	11.9	216
	FL1888-S*	8.8	207	178	707	300		OC	RSIR	11.2	216	
	FL2088-S*	8.8	256	220	874	380			F	CSR	11.4	210
	FL2088-S*	8.8	245	210	836	300		OC	RSCR	11.9	216	
	FL2088-S*	8.8	245	210	836	300		OC	CSIR	11.9	216	
	FL2088-S*	8.8	245	210	836	300		OC	RSIR	11.6	216	



Private Picture Copyright: WWW.MBSM.PRO

Mbsm_dot_pro_private_PDF_P_COM008_105_specTélécharger

14/8/2556

OVERLOAD RELAY - Hitachi Compressor (Thailand) ,Ltd..htm

	FL0739-S*	3.9	94	81	321	270	St		RSIR	7.8	179
	FL0845-S*	4.5	117	100	400	270	St		RSIR	8.1	179
	FL1052-S*	5.2	121	104	413	270	St		RSIR	8.3	179
	FL1152-S*	5.2	136	117	464	260	St		RSCR	8.3	179
	FL1152-S*	5.2	134	115	457	280	St		RSIR	9.3	188
220-240V	FL1157-S*	5.7	136	117	464	240	St		RSIR	8.7	178
50Hz	FL1257-S*	5.7	150	129	512	240	St		RSIR	9.3	181
	FL1257-S*	5.7	173	148	591	240	St		RSCR	9.3	181
	FL1262-S*	6.2	145	124	495	310	St		RSIR	10.5	200
	FL1462-S*	6.2	165	142	563	310	St		RSIR	10.5	200
	FL1462-S*	6.2	185	159	632	310	St		RSCR	11.9	216
	FL1568-S*	6.8	180	154	615	310	St		CSIR	11.5	216
	FL1568-S*	6.8	200	172	683	310	St		RSIR	10.5	200
	FL1568-S*	6.8	200	172	683	310	St		RSCR	10.5	200
	FL1875-S*	7.5	215	184	734	335		OC	RSIR	10.8	211
	FL1875-S*	7.5	208	178	710	310			F RSIR	11.9	216
	FL1888-S*	8.8	207	178	707	300		OC	RSIR	11.2	216
	FL2088-S*	8.8	256	220	874	380			F CSR	11.4	210
	FL2088-S*	8.8	245	210	836	300		OC	RSCR	11.9	216
	FL2088-S*	8.8	245	210	836	300		OC	CSIR	11.9	216
	FL2088-S*	8.8	245	210	836	300		OC	RSIR	11.6	216



Private Picture Copyright : WWW.MBSM.PRO



Copyright : WWW.MBSM.PRO

HITACHI FL1568-SL

.220-240V 50Hz OIL 2008.09.26




SERIAL NO. 22592 HFC-134a

⚠ WARNING | HIGH TEMPERATURE
ELECTRIC SHOCK

DO NOT TOUCH M15

CIRCUIT DIAGRAM

GY...GRAY OR...ORANGE RD...RED PK...PINK
 VT...VIOLET BR...BROWN BL...BLUE BK...BLACK
 GN/YL...GREEN/YELLOW YL...YELLOW
 BK



*THE PLUG TYPE CAPACITOR PARTS, EARTH PARTS ON CIRCUIT DIAGRAM ARE SUBJECTED TO CHANGE ACCORDING MODEL TYPE



Insulation Blowing Gas:
Cyclo-Pentane

N02



Private Picture Copyright : WWW.MBSM.PRO



Private Picture Copyright : WWW.MBSM.PRO



Private Picture Copyright : WWW.MBSM.PRO