

Mbsm.pro, compressor, nht52vbet, 4  
hp, SIAM, 2970w, 12000 btu, 1 ton,  
r22, capillarie 0.064, 220V – 240V  
50Hz, SIAM COMPRESSOR, MITSUBISHI

Category: expertise

written by [www.mbsm.pro](http://www.mbsm.pro) | 17 May 2022



**WARNING**

Read these instructions carefully before attempting to install or use this product. Failure to follow these instructions may result in property damage, personal injury, or death. This product is not to be used for purposes other than those specified in the instructions. For more information, contact your distributor or the manufacturer.

 **SIAM COMPRESSOR  
INDUSTRY CO., LTD.**

**REFRIGERANT COMPRESSOR  
MODEL NHT52VBET**

**MANUFACTURING DATE 06032021**

**POWER SOURCE  
220-240V ~ 50Hz**

**POWER INPUT 2970 W AT 50 Hz**

**LRA 86/94 A**

**REFRIGERANT R-22**

**OIL 1.30 L MPa**

**AP 2.74 MPa**

**SP 10.5 MPa**

**THERMALLY PROTECTED**



Handwritten note in Arabic script: "موتور تبريد" (Refrigerator motor) and "NHT52VBET".

MADE IN THAILAND

Mbsm.pro, compressor, nht52vbet, 4 hp, SIAM, 2970w, 12000 btu, 1 ton, r22, capillarie 0.064, 220V – 240V 50Hz, SIAM COMPRESSOR, MITSUBISHI

---

**Mbsm.pro, Compressor, Toshiba,  
PH160X2-4LU, 12000 btu, 220 v, 1ph,  
r<sub>l</sub>a 6.5 a, f<sub>l</sub>a 40 a, 35 μF**

Category: compressor

written by [www.mbsm.pro](http://www.mbsm.pro) | 17 May 2022

PH160X2-4LU

THERMALLY  
PROTECTED  
R22

PH1 HZ50 V220.240 LRA35  
LOW MPa TP 2.0 AP1.4 DP1.3  
HIGH MPa TP 4.4 AP2.9 DP2.8



50302558

TOSHIBA CORPORATION  
MADE IN JAPAN

**WARNING/DANGER**

FAILURE TO FOLLOW THESE INSTRUCTIONS  
COULD RESULT IN SERIOUS PERSONAL INJURY.

1. FOLLOW RECOGNIZED SAFETY PRACTICES AND WEAR PROTECTIVE GOGGLES.
2. DO NOT OPERATE COMPRESSOR OR PROVIDE ANY ELECTRIC POWER TO THIS UNIT UNLESS THIS COVER IS IN PLACE AND SECURED.
3. DO NOT REMOVE THIS COVER UNTIL ALL ELECTRICAL SOURCES HAVE BEEN DISCONNECTED.
4. IF REFRIGERANT LEAK IS SUSPECTED AROUND TERMINALS RELIEVE ALL PRESSURE FROM SYSTEM BEFORE TOUCHING OR DISTURBING ANYTHING INSIDE THIS TERMINAL BOX.
5. REPAIRS OF COMPRESSOR TERMINAL BOX SHOULD BE MADE BY A QUALIFIED PERSON.

Private Picture Copyright: [WWW.MBSM.PRO](http://WWW.MBSM.PRO)

Mbsm.pro, Compressor, Toshiba, PH160X2-4LU, 12000 btu, 220 v, 1ph, rla 6.5 a, fla 40 a, 35  $\mu$ F