

Mbsm.pro, compressor, Sanyo, Rotary,  
Split system air conditioner,  
Compressors, C-R221H5S, S6231526791,  
24000 btu, R22, 3 hp, 2 ton

Category: air conditioner,compressor  
written by [www.mbsm.pro](http://www.mbsm.pro) | 22 January 2024

**SANYO**



MODEL C-R221H5S

CODE 80687145

SEAL PROTECT



CHINA RESOURCES SANYO (SHENYANG) COMPRESSOR CO., LTD.

沈阳三洋压缩机有限公司

**WARNING-SERVICEMAN**

- 1. FIELD SERVICE LEAK TEST PRESSURE MUST NOT EXCEED 400 PSI.
- 2. THE COMPRESSOR MUST BE GROUNDED.
- 3. DO NOT OPERATE WITHOUT PROTECTIVE COVER OVER TERMINALS.
- DISCONNECT ALL POWER BEFORE REMOVING THE PROTECTIVE COVER.

**CAUTION**

COMPRESSOR HOUSING MAY REACH 100°C WITH THERMAL PROTECTOR.  
APPROVED BY SANYO AND TESTED IN ACCORDANCE WITH JIS T3A.

Private Picture Copyright : [WWW.MBSM.PRO](http://WWW.MBSM.PRO)

Mbsm.pro, compressor, Sanyo, Rotary, Split system air conditioner, Compressors, C-R221H5S, S6231526791, 24000 btu, R22, 3 hp, 2 ton