

# www.mbsm.pro, GREE , Mini Split , Air Conditioner ,Error Codes E6 , How To Fix

Category: Solutions,Tester ok  
written by Jamila | 8 September 2018



The error E6 comes from the engine, it is the electronic engine card if it is an inverter range.

Communication error E6 Between Outside and inside

---

# www.mbsm.pro, FN66Q14G ,Refrigerator Compressors, equivalent in 1/5 HP ,R12, Powerful

Category: Solutions,Tester ok  
written by www.mbsm.pro | 8 September 2018



www.mbsm.pro, FN66Q14G ,Refrigerator Compressors, equivalent in 1/5 HP ,R12,  
Powerful

---

## www.mbsm.pro, COMPRESSOR , 1/5Hp ,EGL75AA , R134A, 155W, LBP, 7.39CM3

Category: Solutions,Tester ok

written by www.mbsm.pro | 8 September 2018



PictureS Mbsm Dot Pro : [www.mbsm.pro](http://www.mbsm.pro)

Low-temperature refrigerator compressor with a cylinder capacity of 7.39cm<sup>3</sup> and a cooling capacity of 155W. Works with refrigerant R134a.

---

## www.mbsm.pro, Compresseur THG1365YGS, R134a ,1/5HP ,230V ,148W

Category: Solutions,Tester ok

written by Jamila | 8 September 2018



PictureS Mbsm Dot Pro : [www.mbsm.pro](http://www.mbsm.pro)


Gamme: Froid Commercial / Industriel  
Type de machine: Divers  
Type de produit: Compresseur  
Sous-type de produit: Compresseur  
Marque: Tecumseh  
Original

---

[www.mbsm.pro](http://www.mbsm.pro), Branchement Unité  
extérieure , LG ,Media , Général ,  
Samsung, Haier , Galanze ,Gree  
,Maxwelle, Vestel

Category: Solutions,Tester ok  
written by Jamila | 8 September 2018

## Outdoor unit wiring image



- 1- Relait de démarrage compressor
- 2- Neutre commun
- 3- Relait de démarrage Fan
- 4- Electro-Vanne Interieur ou inverseur

16

PictureS Mbsm Dot Pro : [www.mbsm.pro](http://www.mbsm.pro)

Branchement Unité extérieure , LG ,Media , Général , Samsung, Haier , Galanze ,Gree ,Maxwelle, Vestel

# [www.mbsm.pro](http://www.mbsm.pro) ,Panasonic , Tested OK ,Refrigeration Compressors ,Industrial Devices

Category: Technologie,Tester ok  
written by Jamila | 8 September 2018



PictureS Mbsm Dot Pro : [www.mbsm.pro](http://www.mbsm.pro)

Panasonic is known throughout the world for manufacturing high quality, reliable products. Our line of refrigeration compressors continues this tradition. Panasonic provides premium compressors for refrigerator manufacturers all over the world. Our compressors are recognized for superior construction, low noise, and most of all reliable performance. From our high efficiency inverter drive compressors to our high capacity QA series, our complete line of compressors are designed to meet the needs for nearly all refrigeration applications.

---

# www.mbsm.pro , Major Cara, climatiseurs , Code Erreur EC , Solution Tester

Category: Solutions,Tester ok  
written by Jamila | 8 September 2018



PictureS Mbsm Dot Pro : [www.mbsm.pro](http://www.mbsm.pro)

Les codes erreurs donnent une approche du type de dysfonctionnement. Faire appel à un professionnel pour les interpréter.

Un code peut provenir de plusieurs causes différentes.

Un dysfonctionnement peut être indiqué par plusieurs codes erreurs

---

# www.mbsm.pro, Electrolux GL75AA Refrigerator 1/5 HP, Compressor Cooling solution for Refrigerators

Category: Technologie,Tester ok  
written by Jamila | 8 September 2018



PictureS Mbsm Dot Pro : [www.mbsm.pro](http://www.mbsm.pro)

www.mbsm.pro, Electrolux GL75AA Refrigerator 1/5 HP, Compressor Cooling solution for Refrigerators

---

# www.mbsm.pro , LG MA42LBJG Refrigerator Compressor 1/6 Hp , Cooling solution for Refrigerators

Category: Technologie, Tester ok  
written by Jamila | 8 September 2018



www.mbsm.pro

Cooling solution for Refrigerators & Commercial Appliances This M-series reciprocating LBP compressor provides complete cooling solution for Domestic & Commercial refrigeration appliances. Compact Size, Silent operation, Low Voltage start ability (LVS) are its prominent features. M-Series compressor caters to 6s quality assurance and has globally proven reliability.

---

# www.mbsm.pro , Embraco FG 75 HAK , true cooler compressor, 1/4hp

Category: Tester ok  
written by www.mbsm.pro | 8 September 2018



www.mbsm.pro

FG 85 HAK,  
FG 75 HAK,  
FFU 80 HAK ,  
FFU 100 HAK,  
FG 65 HAK ,  
EMYE 70 HEP,  
EMT 60 HLP,  
EMT 49 HLP ,  
EMIE 65 HER ,  
EMIE 40 HJP,

EMI 70 HER ,  
EM 55 HNR ,  
EM 45 HNR ,  
EM 30 HHR ,  
EGAS 100 HLR ,  
EGAS 90 HLR ,  
EGAS 80 HLR ,



FG 85 HAK

FG 75 HAK

FFU 80 HAK

FFU 100 HAK

FG 65 HAK

EMYE 70 HEP

EMT 60 HLP

EMT 49 HLP

EMIE 65 HER

EMIE 40 HJP

EMI 70 HER

EM 55 HNR

EM 45 HNR

EM 30 HHR

EGAS 100 HLR

EGAS 90 HLR

EGAS 80 HLR

PictureS Mbsm Dot Pro : www.mbsm.pro



**EMI 70 HER**

**1 / 5 HP**



**EMIE 40 HJP**

**1 / 8 HP**



**EMIE 65 HER**

**1 / 6 HP**



**EMT 49 HLP**

**1 / 6 HP**



**EMT 60 HLP**

**1 / 5 HP**



**EMYE 70 HEP**

**1 / 5 HP**



**FFU 80 HAK**

**1 / 4 HP**



**FFU 100 HAK**

**1 / 4 + HP**



**FG 65 HAK**

**1 / 5 HP**



**FG 75 HAK**

**1 / 4 HP**



**FG 85 HAK**

**1 / 4 + HP**



**EGAS 80 HLR**

**1 / 4 + HP**



**EGAS 90 HLR**

**1 / 4 HP**



**EGAS 100 HLR**

**1 / 4 + HP**



**EM 30 HHR**

**1 / 10 HP**



**EM 45 HNR**

**1 / 8 HP**



**EM 55 HNR**

**1 / 6 HP**

PictureS Mbsm Dot Pro : [www.mbsm.pro](http://www.mbsm.pro)



**Embraco FG 75 HAK**

BEAB Approved

THERMALLY PROTECTED **220-240V~**  
**50Hz**

7 LRA  
R. 134g PH

JOINVILLE-SC  
MADE IN BRAZIL

NO START WITHOUT STARTING DEVICE

513207808 F97LQ4CP

**Embraco FG 75 HAK**

BEAB Approved

THERMALLY PROTECTED

7 LRA

R 134g PH

**220-240V~**

**50Hz**

JOINVILLE-SC  
MADE IN BRAZIL

NO START WITHOUT STARTING DEVICE

513207808 FABI 25/MAR/97 F97LQ4CP

