

Mbsm.pro, compressor, Tecumseh, TWB1380yGR, TW151-GR-601, 1/3 hp, r134a, THG1374YDS, TSB1390YGS, AEA1380YXA, TSA1380YAS, TSA1380YCS, TSA1380YDS, TSA1380YGS, TSA1380YMS, TWB1380YDS, TWB1380YDS, TWB1380YGR, TWB1380YLS, TWB1390YKS, TWB1390YZS, Embraco, FFI10HAK, FFI10HAKW, FFUS100HAK, THG1374YDS (1/5+ or 1/4), LBP, 1PH, 220 V, 50 Hz, 847 btu

Category: compressor

written by www.mbsm.pro | 24 February 2022

	1/3	EGAS100HLR	855	1050	Estático	LBP	EGAS100HLR / EGX100HLC / EGZS100HLP / FGS100HA EGS100HLC / EGY100HLP / FFI10HAK / FGS100HAS EGU100HLC / EGYS100HLP / FFI10HAKW / FGS100HAW EGU100HLCW / EGZ100HLP / FFI10HBX / NE1121Z EGUS100HLP / EGZS100HLC / FFU100HAK / NE2121Z EGUS100HLPW / EGZS100HLCW / FFU100HAKW		TPHH1410Y / AE1410Y / AEA2410YXA CAE2410Y / TPA1410YXA
	1/3	FFUS100HAK	847	1009	Estático	LBP	FFI10HAK / FFI10HAKW		THG1374YDS / TSB1390YGS / AEA1380YXA / TSA1380YAS / TSA1380YCS / TSA1380YDS / TSA1380YGS / TSA1380YMS / TWB1380YDS / TWB1380YDS / TWB1380YGR / TWB1380YGS / TWB1380YLS / TWB1390YKS / TWB1390YZS
	1/3+	FFI12HBX FFU130HAX FFUS130HAX	1090 1055 1055	1190 1250 1250	Forçado	LBP	FFI12HBK / NE1130Z FFU130HAXW / FFI12HBKW / NE2130Z FFI12HAX / FFI12HBXW / FFI12HBK	TCB0012	TPH1413Y / AE1412Y / AEA2413YXA TPG1413Y / CAE2412Y CAE2414Y
	1/3+	FFU160HAX	1275	1533	Forçado	LBP	FFI12HBX / FFU130HAXW / NE2130Z / FFI12HBXW / NE1130Z		TPH1415Y / AJA2419YXA

Private Picture Copyright : WWW.MBSM.PRO

Mbsm.pro, compressor, Tecumseh, TWB1380yGR, TW151-GR-601, 1/3 hp, r134a, THG1374YDS, TSB1390YGS, AEA1380YXA, TSA1380YAS, TSA1380YCS, TSA1380YDS, TSA1380YGS, TSA1380YMS, TWB1380YDS, TWB1380YDS, TWB1380YGR, TWB1380YGS, TWB1380YLS, TWB1390YKS, TWB1390YZS, Embraco, FFI10HAK, FFI10HAKW, FFUS100HAK